



BRDR200TECH

Technical Instructions	Machine Compatibility	OEM Info	Tools	1
------------------------	-----------------------	----------	-------	---

*See page 8*

Part Number: DR-200  
Yield @ 20,000 pgs  
Pages/Min.: 6  
Resolution: 600x600 dpi

Phillips Screwdriver  
Small flat blade Screwdriver

**Supplies Required:**  
Cotton Swab  
99% Alcohol  
Replacement Drum

**CORPORATE  
LOS ANGELES, USA**  
US 1 800 394.9900  
Int'l +1 818 837.8100  
FAX 1 800 394.9910  
Int'l +1 818 838.7047

**ATLANTA, USA**  
US 1 877 676.4223  
Int'l +1 770 516.9488  
FAX 1 877 337.7976  
Int'l +1 770 516.7794

**DALLAS, USA**  
US 1 877 499.4989  
Int'l +1 972 840.4989  
FAX 1 877 774.1750  
Int'l +1 972 840.1750

**MIAMI, USA**  
US 1 800 595.429  
Int'l +1 305 594.3396  
FAX 1 800 522.8640  
Int'l +1 305 594.3309

**NEW YORK, USA**  
US 1 800 431.7884  
Int'l +1 631 345.0121  
FAX 1 800 431.8812  
Int'l +1 631345.0690

**SANFORD, USA**  
US 1 800 786.9049  
Int'l +1 919 775.4584  
FAX 1 800 786.9049  
Int'l +1 919 775.4584

**TORONTO, CAN**  
CAN 1 877 848.0818  
Int'l +1 905 712.9501  
FAX 1 877 772.6773  
Int'l +1 905 712.9502

**BUENOS AIRES, ARG**  
ARG 0810 444.2656  
Int'l +011 4583.5900  
FAX +011 4584.3100

**MELBOURNE, AUS**  
AUS 1 800 003. 100  
Int'l +62 03 9561.8102  
FAX 1 800 004.302  
Int'l +62 03 9561-7751

**SYDNEY, AUS**  
AUS 1 800 003.100  
Int'l +62 02 9648.2630  
FAX 1800 004.302  
Int'l +62 02 9548.2635

**MONTEVIDEO, URY**  
URY 02 902.7206  
Int'l +5982 900.8358  
FAX +5982 908.3816

**JOHANNESBURG, S.A.**  
S.A. +27 11 974.6155  
FAX +27 11 974.3593

**Photo 1**




**Step 1**

Remove the two screws from the top of the drum unit.

*(See Photo 1)*

**Photo 2**



**Step 2**

Using a small flat blade screwdriver, release the two locking tabs located just below the two screws.

*(See Photo 2)*

**Photo 3**



**Step 3**

Locate the metal toner cover in the two slots on top of the cartridge.

*(See Photo 3)*













Photo 30

**Step 28**

Place the transfer roller onto the drum.

(See Photo 30)

Photo 31

**Step 29**

Place the toner hopper agitator drive gear onto the cartridge.

(See Photo 31)

Photo 32

**Step 30**

Place the cartridge cover on top of the cartridge and press down until the locking tabs hold the cover in place. Install the two screws that also hold the cover.

(See Photo 32)

Photo 33

**Step 31**

Flip the cartridge upside down. Use your finger to slide the metal toner fill cover until the metal cover is just covering the toner fill opening.

(See Photo 33)

**NOTE:** If the cover is out of position, an insufficient amount of toner will get to the toner hopper and light print will occur.

**Step 32**

Test cartridge.

**RESETTING THE DRUM COUNTER****Step 1**

Install the jagged end of the clear reset sheet into the cartridge between the drum and transfer roller.

(See Photo 1)

Photo 1

**Step 2**

Rotate the drum so the reset sheet is fed into the cartridge and the end of the sheet is flush with the end of the cartridge with the jagged end of the sheet sticking out the top of the cartridge. (See Photo 2)

**NOTE:** Once the sheet is fed through the printer, the machine will reset the drum counter.

Photo 2



Need help with a particular remanufacturing problem?

Call the Technical Resource Center from  
8am - 5pm PST: 800 394.9900

# Remanufacturing the Brother 720 Drum Unit

The Brother HL 720 engine was utilized in a wide variety of printer, fax and multi-function machines. It is now discontinued but a large number of these engines remain in the field. The Brother HL 720 is capable of printing at only 6 pages per minute at 600 x 600 dpi and consists of separate toner and drum units.

The toner unit, OEM P/N TN-200 is nothing more than a tube of toner that holds 90 grams of toner and yields only 2,200 pages. The drum unit, P/N DR-200 contains the developer roller, drum, and transfer roller and yields 20,000 pages.



**DR-200**

The biggest obstacle in the remanufacturing of the drum unit is trying to find a developer roller that is not damaged.

Streaking caused by worn developer rollers is a constant problem for those who remanufacture the DR-200 drum units. Multiple cores may need to be screened in order to find a good roller.

Due to the current unavailability of replacement rollers, many people pass on remanufacturing this cartridge. Replacement parts are just now becoming available, allowing the remanufacturer to add these cartridges to their product mix. Good profit margins make it attractive to those willing to accept the challenge.

## Machine Compatibility

Machine Model	OEM Number	Engine
Brother HL-1020	TN-200	Brother 720
Brother HL-720	TN-200	Brother 720
Brother HL-730	TN-200	Brother 720
Brother HL-730 +	TN-200	Brother 720
Brother HL-730 DX	TN-200	Brother 720
Brother HL-760	TN-200	Brother 720
Brother HL-760 +	TN-200	Brother 720
Brother Intellifax 2550 ML	TN-200	Brother 720
Brother Intellifax 2600	TN-200	Brother 720
Brother Intellifax 2660	TN-200	Brother 720
Brother Intellifax 2750	TN-200	Brother 720
Brother Intellifax 3350	TN-200	Brother 720
Brother MFC 4300	TN-200	Brother 720
Brother MFC 4340	TN-200	Brother 720
Brother MFC 4600	TN-200	Brother 720
Brother MFC 6650 MC	TN-200	Brother 720
Brother Intellifax 3550	TN-5000	Brother 720
Brother Intellifax 3650	TN-5000	Brother 720
Brother Intellifax 3750	TN-5000	Brother 720
Brother MFC 3750	TN-5000	Brother 720
Brother MFC 4350 MC	TN-5000	Brother 720
Brother MFC 4450	TN-5000	Brother 720
Brother MFC 4550	TN-5000	Brother 720
Brother MFC 4550 +	TN-5000	Brother 720
Brother MFC 4650	TN-5000	Brother 720
Brother MFC 6550 MC	TN-5000	Brother 720
Brother MFC 7550 MC	TN-5000	Brother 720
Brother MFC 7650 MC	TN-5000	Brother 720
Brother MFC 7750	TN-5000	Brother 720
Brother PPF 3650 ML	TN-5000	Brother 720
Danka Omnifax L620	TN-5000	Brother 720
Omnifax L620	TN-5000	Brother 720
Omnifax L620e	TN-5000	Brother 720